




















Parts list

 <p>A x 4PCS</p>		 <p>B x 4PCS</p>	
 <p>D x 4PCS</p>		 <p>E x 4PCS</p>	
 <p>F x 4PCS</p>	 <p>G x 4PCS</p>	 <p>H x 4PCS</p>	 <p>I x 8PCS</p>
 <p>J x 1PC</p>	 <p>M6x12mm K x 64PCS</p>	 <p>M6x38mm L x 16PCS</p>	 <p>M x 8PCS</p>
 <p>N x 1PC</p>	 <p>O x 1PC</p>	 <p>P x 4PCS</p>	 <p>Q x 4PCS</p>
 <p>R x 96PCS</p>			


STEP 1




STEP 3




STEP 2




STEP 4




STEP 5




STEP 7




STEP 6



STEP 8



STEP 9



STEP 10

